

FIG. 1




FIG. 2

FIG. 3




FIG. 3




FIG.4

FIG. 5




FIG. 6





FIG. 6

FIG. 7



DIGI-DATA PC Controller 3:12pm

Digi Data Job: Job

Select Job: [01007] **Add Job** **Print**

Measure:
☐ Damaged vehicle
☒ Required vehicle
Start Recording

Vehicle: Nissan Maxima **Reg No:** NIS 001 **Client:** Mr G. Fellows **Date:** 9 Aug 98 **File:** X-487

Active Quadrant: ☐ A ☐ B ☐ C ☐ D

Measurement Method: ☐ Vehicle Data ☒ Comparison **Unit:** mm

	Vehicle Data				Damaged		Required	
	Ref	D/S	P/S	D/S	P/S	D/S	P/S	
Delum. Height at Cross Bar [203]								
Width	G	1300	0					
Length	C	970	970					
Height	C	370	370					
Diagonal - 21"	C	1486	1486					

Comment: Driver side front tyre badly worn.

Close

Digi Data Group **DIGI-DATA PC Controller**

FIG.8

VEHICLE MEASUREMENT REPORT

	VEHICLE _____	DATE: _____
	REG NO: _____	JOB: _____
	CLIENT: _____	FILE: _____

DATUM HEIGHT AT CROSS BAR	A	VEH.DATA		DAMAGED		REPAIRED		
		REF	D/S	P/S	D/S	P/S	D/S	P/S
203								
WIDTH	O	1200		0		0		
LENGTH	C	970	970	-15	0	-1	0	
HEIGHT	C	370	370	-7	-1	-1	-1	
DIAGONAL	C	1486	1486	-8	0	-1	0	

COMMENTS: Driver side front tyre badly worn.

DATUM HEIGHT AT CROSS BAR	B	VEH.DATA		DAMAGED		REPAIRED		
		REF	D/S	P/S	D/S	P/S	D/S	P/S
WIDTH								
LENGTH								
HEIGHT								
DIAGONAL								


COMMENTS:

DATUM HEIGHT AT CROSS BAR	C	VEH.DATA		DAMAGED		REPAIRED		
		REF	D/S	P/S	D/S	P/S	D/S	P/S
WIDTH								
LENGTH								
HEIGHT								
DIAGONAL								

COMMENTS:

DATUM HEIGHT AT CROSS BAR	D	VEH.DATA		DAMAGED		REPAIRED	
		REF	D/S	P/S	D/S	P/S	D/S
WIDTH	A	1478		0		0	
LENGTH	B	844	844	-22	0	0	0
HEIGHT	C			89	89	89	89
DIAGONAL	D	1662	1662	-11	0	-1	0

COMMENTS:



Operator: _____

Signed: _____

Date: _____

FIG.9